



Megaplot, J. Wójcicki, M. Jagła - Spółka Jawna
ul. Chemiczna 12, 41-205 Sosnowiec, Poland
VAT UE: PL 6442953303, NIP: 644-29-53-303
Phone: +48 693 707 575, +48 32 291 93 41
Fax: +48 32 291 08 72, office@foamcutter.pl

Bank Account: Fortis Bank Polska S.A.
ul. Postępu 15, 02-676 Warszawa, Poland
S W I F T / B I C : P P A B P L P K
PLN: PL 32 1600 1055 0002 3211 7437 3001
EUR: PL 47 1600 1055 0002 3211 7437 3022
USD: PL 74 1600 1055 0002 3211 7437 3021

12-month Warranty Certificate for MegaPlot Fast Wire XTR Cutters

The MegaPlot Fast Wire Cutter you have chosen to purchase is supplied with a manufacturer's limited warranty granted by Megaplot J. Wojcicki M. Jagła SJ (MP).

This limited warranty covers any manufacturing flaws that may occur and any subsequent labour that is required during the warranty period for repair.

Megaplot will, at our discretion, either repair, rebuild or replace the faulty equipment or parts in accordance with the terms laid out below.

The warranty covers a 12 month period and commences from the date on which the equipment was installed; warranty repairs will not extend the warranty period.

The warranty covers the parts and materials required to repair, rebuild or replace the machine, at the option of Megaplot, for a period of 12 months and the cost of labour needed to repair or rebuild the machine for a period of 12 months.

The fast wire XTR cutter requires careful handling since it uses precision parts that have been through a rigorous quality management process.

The owner's warranty covers only the following:

- Flaws caused by materials or labour in the machine in existence at the time of assembly.
- Faults occurring in normal use as defined in the owner's manual, and strictly providing that our instructions on installation, use and maintenance have been adhered to.
- The person who originally purchased the machine who can provide original proof of purchase.

The extent of this warranty does not cover any of the following:

- Modifications made to machine or components without the consent of Megaplot.
- Faults resulting from natural wear and tear, use in conditions for which the machine is not intended, corrosion, or damage incurred during loading or shipping not provided by Megaplot, or by accident, fire, flood, war or acts of God.
- Maintenance activities, such as cleaning, lubricating or normal checking of parts; or installation procedures that customers can do themselves and that do not require dismantling or any reassembling of the machine.
- Repairs performed by someone other than an authorised Megaplot representative.
- Repairs due to limitations or corrections in the machine's software.
- Repairs to consumable or cosmetic items, e.g., grips, seals, labels.
- Repairs performed on the machine missing a serial number or with a serial tag that has been altered or removed.
- Service calls to correct installation of the machine or instruct owners how to use the machine.
- Pick-up, delivery, or shipping charges involved with repairs.